



HAZMAT / TOXIC SPILL



REPORTED



ENGAGED



NO

DCST-024-HMAT-03



SOUNDS OF DAMAGE  
N/A

FLAGS TO DISPLAY

REPORTED

ENGAGED


NO

<b>HM</b> Paint Thinner	TIME <u>1629</u> NUMBER <u>3</u>
	FROM                      TO
X <u>FM</u> - INV - SL      _____	
_____ DCRS 2	
_____ DCRS 3	
_____ DCRS 5      X	
_____ DCC	
COMPT. #/NAME <u>2-426-6-Q</u>	
FRAME _____	
REMARKS:	
OVHD	
PORT	STBD
AFT →	DECK
BOUNDARIES	S    P    P    S
FB - SB - FLB - CB	

<b>HM</b>	TIME <u>1633</u> NUMBER <u>4</u>
FROM                      TO	
X <u>FM</u> - INV - SL      _____	
_____ DCRS 2	
_____ DCRS 3	
_____ DCRS 5      X	
_____ DCC	
COMPT. #/NAME <u>2-426-6-Q</u>	
FRAME _____	
REMARKS:	
OVHD	
PORT	STBD
AFT →	DECK
BOUNDARIES	S    P    P    S
FB - SB - FLB - CB	

<b>HM</b>	TIME <u>1701</u> NUMBER <u>5</u>
FROM                      TO	
X <u>FM</u> - INV - SL      _____	
_____ DCRS 2	
_____ DCRS 3	
_____ DCRS 5      X	
_____ DCC	
COMPT. #/NAME <u>2-426-6-Q</u>	
FRAME _____	
REMARKS:	
OVHD	
PORT	STBD
AFT →	DECK
BOUNDARIES	S    P    P    S
FB - SB - FLB - CB	

# Three different examples of manual plotting




HM

Line

1629

2-426-6-Q



Box

2-426-6-Q

~~HM~~

Oil

1629

1633

1701

Column

REPORTED

TIME 1629 NUMBER 3

HM FROM X TO

Part FROM TO

Trimmer FROM TO

COMPT. #NAME 3-625-0

FRAME

REMARKS

3D Box Diagram

BOUNDARIES S P D S

FB - SB - FLB - CB

ENGAGED

TIME 1633 NUMBER 4

HM FROM X TO

Part FROM TO

Trimmer FROM TO

COMPT. #NAME 3-625-0

FRAME

REMARKS

3D Box Diagram

BOUNDARIES S P D S

FB - SB - FLB - CB

NO

TIME 1701 NUMBER 5

FROM X TO

Part FROM TO

Trimmer FROM TO

COMPT. #NAME 3-625-0

FRAME

REMARKS

3D Box Diagram

BOUNDARIES S P D S

FB - SB - FLB - CB