DCST-027-RAD-01

RADIATION HAZARD

SOUNDS OF DAMAGE
N/A

FLAGS TO DISPLAY

REPORTED

NUC

TIME 1629 NUMBER 3

FROM TO

X FM - INV - SL
DCRS 2
DCRS 3
DCRS 5 X
DCC

COMPT. #/NAME 1-426-0-Q

FRAME

REMARKS:



BOUNDARIES	S	P	P	S
FB - SB - FLB - CB				

ENGAGED

NUC

TIME 1633 NUMBER 4

FROM TO

X FM - INV - SL
DCRS 2
DCRS 3
DCRS 5 X
DCC

COMPT. #/NAME 2-426-0-Q

FRAME

REMARKS:



BOUNDARIES	S	P	P	S
FB - SB - FLB - CB				

NO

NUC

TIME 1701 NUMBER 5

FROM TO

X FM - INV - SL
DCRS 2
DCRS 3
DCRS 5 X
DCC

COMPT. #/NAME 2-426-0-Q

FRAME

REMARKS:



BOUNDARIES	S	P	P	S
FB - SB - FLB - CB				

Three different examples of manual plotting



NUC

1629

Line

1-426-0-Q

NUC

~~1629~~

1633

Box

1-426-0-Q

~~NUC~~

~~1629~~

~~1633~~

1701

Column