



HEAT TRANSFER



REPORTED



ENGAGED



NO

DCST-006-HT-01



FLAGS TO DISPLAY



SOUNDS OF DAMAGE
TRACK 14 RAPID
BURNING A FIRE

REPORTED

<u>HT</u>	TIME 1629	NUMBER 3
	FROM	TO
	<input checked="" type="checkbox"/> FM-INV (SL)	
	DCRS 2	
	DCRS 3	<input checked="" type="checkbox"/>
	DCRS 5	
	DCC	
COMPT. #/NAME 2-446-6-Q		
FRAME _____		
REMARKS:		
	OVHD	
	PORT	STBD
	AFT →	← FWD
	DECK	
BOUNDARIES		S P P S
FB - SB - FLB - CB		


ENGAGED

—	TIME 1633	NUMBER 4
	FROM	TO
	<input checked="" type="checkbox"/> FM-INV (SL)	
	DCRS 2	
	DCRS 3	<input checked="" type="checkbox"/>
	DCRS 5	
	DCC	
COMPT. #/NAME 2-446-6-Q		
FRAME _____		
REMARKS:		
	OVHD	
	PORT	STBD
	AFT →	← FWD
	DECK	
BOUNDARIES		S P P S
FB - SB - FLB - CB		

NO

—	TIME 1701	NUMBER 5
	FROM	TO
	<input checked="" type="checkbox"/> FM-INV (SL)	
	DCRS 2	
	DCRS 3	<input checked="" type="checkbox"/>
	DCRS 5	
	DCC	
COMPT. #/NAME 2-446-6-Q		
FRAME _____		
REMARKS:		
	OVHD	
	PORT	STBD
	AFT →	← FWD
	DECK	
BOUNDARIES		S P P S
FB - SB - FLB - CB		

Three different examples of manual plotting



REPORTED

TIME 1629 NUMBER 3

HT

FROM X FM - INV (SL) TO

DCRS 2

DCRS 3 X

DCRS 5

DCS

COMPT. #NAME 2-446-6-Q

FRAME

REMARKS:

OVRD

PORT

AFT → DECK

← FWD

STBD

BOUNDARIES S P P S

FB - SB - FLB - CB

ENGAGED

TIME 1633 NUMBER 4

HT

FROM X FM - INV (SL) TO

DCRS 2

DCRS 3 X

DCRS 5

DCS

COMPT. #NAME 2-446-6-Q

FRAME

REMARKS:

OVRD

PORT

AFT → DECK

← FWD

STBD

BOUNDARIES S P P S

FB - SB - FLB - CB

NO

TIME 1701 NUMBER 5

HT

FROM X FM - INV (SL) TO

DCRS 2

DCRS 3 X

DCRS 5

DCS

COMPT. #NAME 2-446-6-Q

FRAME

REMARKS:

OVRD

PORT

AFT → DECK

← FWD

STBD

BOUNDARIES S P P S

FB - SB - FLB - CB