RUPTURE - FM

REPORTED ENGAGED NO

SOUNDS OF DAMAGE
TRACK 9 LOW PRESSURE
PIPE RUPTURE

DCST-008-FM-01

FLAGS TO DISPLAY

REPORTED

FM

1" Crack

TIME 1629 NUMBER 3

FROM	TO	
X	FM – INV - SL	
	DCRS 2	
	DCRS 3	
	DCRS 5	X
	DCC	

COMPT. #/NAME 2-426-2-K

FRAME

REMARKS:



BOUNDARIES	S	P	P	S
FB - SB - FLB - CB				

ENGAGED

FM

Jubilee

TIME 1633 NUMBER

FROM	TO	
X	FM – INV - SL	
	DCRS 2	
	DCRS 3	
	DCRS 5	X
	DCC	

COMPT. #/NAME 2-426-2-K

FRAME

REMARKS:



BOUNDARIES	S	P	P	S
FB - SB - FLB - CB				

NO

FM

TIME 1701 NUMBER 5

FROM	TO	
X	FM – INV - SL	
	DCRS 2	
	DCRS 3	
	DCRS 5	X
	DCC	

COMPT. #/NAME 2-426-2-K

FRAME

REMARKS:



BOUNDARIES	S	P	P	S
FB - SB - FLB - CB				

Three different examples of manual plotting